



8 7 6 5 4 3 2 1

SAME SLOPE CONNECTION. (IF MAIN BOARD IS IN TAKEUP, IB-802 IS IN TAKEUP).



INSTALL CB-5000AM MODULE WITH TERMINALS TOWARD CENTER OF CB-5101M\CB-5201RM BOARD.

INVERSE SLOPE CONNECTION. (IF MAIN BOARD IS IN TAKEUP, IB-802 IS IN PAYOUT).



COLLITEK		COIL TECHNOLOGY, INC.
IB-802 TO CB-5201RM\CB-5101M		9350 RITTMAN RD.
D		WADSWORTH, OHIO 44281
DRAWING NUMBER: IBS100.P01		
DATE: 4/16/95		
PAGE 1 OF 1		

8 7 6 5 4 3 2 1